

# **MDTools 770 SP2**

**Applicability:** MDTools 770 NW, SA, and MDTools 770S

## **Issues Resolved:**

### **Part Model**

#### **Insert from HyDraw Schematics**

1. When clicked, the Insert button is not disabled, allowing multiple clicks.

#### **Shrink Wrap**

2. Shrink-wrapped model alters Drill Holes Step0 depth and Counterbore Depth for Drill Holes.

#### **Orifice Plug**

3. Error when adding merged orifice to a Footprint Child Drill with O-ring or counterbore.

#### **Undercut**

4. When inserting concentric undercut to a Sun Cavity, wrong diameter value is indicated.

#### **Replace**

5. In a footprint, when one of the drills with O-ring counterbore is replaced, the O-ring counterbore disappears from all other drills.

#### **O-ring**

6. Unable to edit or delete Mandatory O-rings.

#### **Edit**

7. When a child drill is edited for changing the Inclination angle, the Origin displays incorrectly at the Footprint Parent Drill.

#### **Generate Machining ID**

8. Machining ID is not retained for the replaced cavity.

#### **Set Assembly Constraints.**

9. To select the Top face of the CAD Model requires two clicks instead of one.

### **Drawing**

#### **Auto Dimension**

10. When an additional Base view displaying hidden details is placed in the drawing sheet, then unable to Auto Dimension the block views.
11. In a specific case, one Co-ordinate axis value is not created for a cavity.

## **Assembly**

### **Assemble Component**

12. When LS depth is modified for the Sun Cavity, the CAD Model assembles incorrectly.
13. Merged Orifice plugs assemble upside down.

### **Set Assembly Constraints**

14. For Assembly files (\*.iam), incorrect assembly constraints are created.

Date: Nov 01, 2018.

## **MDTools 770 Hotfix 03**

Applicability: MDTools 770 NW, SA and MDTools 770S with SP1.

### **Issue Resolved**

Incompatibility of iParts with MDTools Assembly Commands.

Date: Aug 22, 2018.

## **MDTools 770 Hotfix 01**

Applicability: MDTools 770 NW, SA and MDTools 770S with SP1.

### **Issue Resolved**

In a specific case, Design Check generates incorrect Clearance (Wall thickness) report for Sun Cavity.

Date: Jul 23, 2018.

## MDTools 770 SP1

**Applicability:** MDTools 770 NW, SA and MDTools 770S

### Issues Resolved

#### Part Model

##### Modify Block

1. After removing material from a block, the cavity does not move.

##### Export

2. When exporting a block as a \*.mbxml file, an Error message displays.

##### Insert Cavity

3. When the Insert button is clicked multiple times, Inventor freezes.

##### X-Ports

4. With Energy Efficiency, Tank Type Connection option, an under-sized drill diameter is recommended.

##### Copy Multiple

5. For a specific block in Feature Mode, few cavities are not copied.

##### Orifice

6. When inserting merged orifice to VC10-2 cavity, an Error message displays.

##### Replace Cavity

7. In the Fraction format with the Retain Drill Diameter option selected, the drill diameter value is not retained.

##### Angular Connection

8. When an angular connection is made between cavities placed at a specific location, an Error message displays.

##### Move

9. Move command does not display the actual precision of the location of X & Y, but displays the applied precision as in MDTools Settings.

##### Edit Cavity

10. In Cavity Dimensions, Fraction values from Library displays as decimals.

##### Stretch

11. When stretching a drill up to reference, the decimal precision set in MDTools Settings is not used.

### **Add Drill**

12. For large manifolds, the Add Drill command is slow.

### **Manage Engraving**

13. Engravings do not move, when it is reconnected to a cavity in the block.

### **Connection Check**

14. Incorrect Dead Area Step is highlighted for Connection error.

### **Schematic Check**

15. After Merged Orifice is added to Footprint drills, the Footprint report is incorrect.

### **Color**

16. In Feature Mode, the cavity with multiple ports on same step, does not display the NET color.

### **Generate Machining ID**

17. With Scheme 5, the changed Face Name is not retained.
18. With Scheme 5, on regenerating Machining ID, earlier assigned Machining IDs are not retained.

### **Create Machining Drawing**

19. MDTools PART Model Browser freezes and displays in the Drawing environment.

### **Components and Parts List**

20. When a block has only one cavity, the Components and Parts list is not created.

### **Edit Machining Chart Formats**

21. When selecting a Machining Chart format, an Error message displays.

### **Show All Nets (Model Browser)**

22. When clicking Show All Nets after changing a specific NET color, an Error message displays.

## **Drawing**

### **Create Views**

23. Drawing Views of assembled block (\*.iam file) displays a transparent box around the engravings.

### **Show Internal Details**

24. Internal view of the block, which is behind the Cutout, does not display.

### **Show Component ID**

25. When "&" is present in an ID, the Component ID displays incorrect characters in the Drawing view.
26. Component ID does not display individual drill holes in the drawing.

### **Create Balloons**

- 27. Slot Leader location is incorrect.

### **Machining Chart**

- 28. After switching from Component ID to Machining ID, the number of items displayed is incorrect.
- 29. For Numeric and Alphanumeric IDs, Cavity ID does not sort correctly.

## **Assembly**

### **Assemble Component**

- 30. In the CAD Model selection dialog, subfolders are not listed.
- 31. In Inventor 2018, the Expander Plug Model created in Inventor 2017 is assembled upside down.
- 32. When Assembly is updated after removing Component Models on a block, there is instability.
- 33. CAD File linked to accessory in HyDraw, is not getting assembled.

### **Assemble Plugs**

- 34. Unable to assemble multibody plugs.

Date of Release: Jun 13, 2018