HyDraw CAD 2019 SP1 IT

Applicability:

HyDraw CAD 2019.0.0.6 x64 IT

Issues Resolved:

- 1. Moving an external port or its port name, snaps to the corner of the envelope.
- 2. When switching between opened drawings, closed work windows of HyDraw Library Explorer, HyDraw Property Manager, Export to MDTools pop up.
- 3. Unable to open dxf file created in HyDraw.
- 4. Repeated adding/editing of Library symbols increases the saving time of the schematic.
- 5. Replaced external port does not reorient with respect to the envelope.
- 6. Zero length Connection line appears in schematic check.
- 7. Instability with unconfigured AccessDatabaseEngine_X64.
- 8. File name in Drawing tab does not change, when using the Save As command.
- 9. When Sub-System has an accessory with reassigned balloon type or Item ID, a larger balloon is displayed.
- 10. Exploding Sub-System to components more than once, creates some balloons at drawing origin.
- 11. When reassigning Item ID, envelope in Sub-System is not numbered first.
- 12. Jumping reference deleted along with the connection line, recreated after merging any two connection lines.
- 13. Update From Excel, not updating by Part Number.
- 14. Using the AutoCAD Trim command with connection line results in instability.
- 15. Drawing Update displays exception when opening an old drawing.
- 16. Edit Symbol Port: After modifying ports names, clicking the Cancel button saves changes.
- 17. The yellow Update icon does not appear, when a column is introduced in Part List.
- 18. In some cases, error when closing the drawings.
- 19. Hose list does not display Assembly ID of Hoses.
- 20. Mirroring a schematic second time results only in mirroring of HyDraw texts.
- 21. Update Parts List: When quantity values change, the corresponding row gets deleted in case of grouped items.
- 22. Inserting custom External Port displays error.
- 23. Export to MDTools command fails when items have same item ID.
- 24. When the drawing includes a Parts List, the Convert to HyDraw command causes instability.
- 25. When the drawing includes a Parts List, joining a custom Connection Line (e.g. Line1) to another Custom Connection Line's tip (end) displays error and causes instability.
- 26. HyDraw Library Explorer: Component tab slightly overlaps.
- 27. When an Item ID is manually positioned, the Reassigned Item ID is not at its new location.
- 28. Export to MDTools: Order of CAD models linked to a model are incorrect.
- 29. Copied Sub-System, takes new balloon type from HyDraw option for Components.
- 30. In Update Parts List, the yellow Update icon does not appear for,
 - a. Components Accessories.
 - b. System Accessories.
 - c. External Port Accessories.
 - d. Item ID/Accessory ID edited by double click.
 - e. Grouped Hose ID.
 - f. Multiple Parts List.

- 31. In Update Parts List,
 - a. Value of design properties is not updated.
 - b. Currency data types are not updated correctly.
- 32. Updating the earlier version drawing displays error.
- 33. Instability when deleting/renaming the "C:\VEST" folder.
- 34. For drawing with split Parts List, using the Save As command causes instability.
- 35. In some cases, drawing Envelope Line across Connection lines causes the connection line to be inclined and introduces duplicate ports.
- 36. Stretching the envelope, when an envelope line segment is not straight, moves Ports to the opposite side of the envelope line.

Date: Feb 14, 2019.