Steps to create a HyDraw CAD drawing view inside a Solidworks drawing space:

1. Click **File → New → Drawing**.
2. Click OK.
3. Select a required sheet size.
4. Click OK.
5. Click **Annotation**.
6. Click **Insert Block** from Blocks drop-down list.

7. Click **Browse…** button from Model browser.

8. Select **AutoCAD DWG Blocks (*.dwg)** option from file type drop-down list.

9. Select the folder containing dwg file.
10. Select the dwg file.
11. Click **Open**.

12. Place the drawing view in the required location and press **Esc** button.

Switching off HyDraw CAD drawing layer visibility:

1. Select the inserted drawing view.
2. From **Model browser – Layer**, select **Format** to switch off the HyDraw CAD drawing layers visibility.