MDTools® Library Manager 2020 Hotfix 01

Applicability: MDTools Library Manager 2020

Issues Resolved:

1. Construction Ports changed to Cartridge Valve type after using the Import Cavity Data command though retained construction port attributes in MDTools.

2. O-ring machining sequence did not save changes.

3. MDTools Library Manager instability with higher display resolutions when using the Edit Outline command.

4. Display at 125% had some compatibility issues.

5. Edit Undercut did not show new undercuts in the Net List until Edit Undercut was closed and reopened.

Date: July 8, 2022