

HyDraw CAD 2019 SP1 EN

Applicability:

HyDraw CAD 2019.0.0.5 x64 EN

Issues Resolved:

1. Moving an external port or its port name, snaps to the corner of the envelope.
2. When switching between opened drawings, closed work windows of HyDraw Library Explorer, HyDraw Property Manager, Export to MDTools pop up.
3. Unable to open dxf file created in HyDraw.
4. Repeated adding/editing of Library symbols increases the saving time of the schematic.
5. Replaced external port does not reorient with respect to the envelope.
6. Zero length Connection line appears in schematic check.
7. Instability with unconfigured AccessDatabaseEngine_X64.
8. File name in Drawing tab does not change, when using the Save As command.
9. When Sub-System has an accessory with reassigned balloon type or Item ID, a larger balloon is displayed.
10. Exploding Sub-System to components more than once, creates some balloons at drawing origin.
11. When reassigning Item ID, envelope in Sub-System is not numbered first.
12. Jumping reference deleted along with the connection line, recreated after merging any two connection lines.
13. Update From Excel, not updating by Part Number.
14. Using the AutoCAD Trim command with connection line results in instability.
15. Drawing Update displays exception when opening an old drawing.
16. Edit Symbol Port: After modifying ports names, clicking the Cancel button saves changes.
17. The yellow Update icon does not appear, when a column is introduced in Part List.
18. In some cases, error when closing the drawings.
19. Hose list does not display Assembly ID of Hoses.
20. Mirroring a schematic second time results only in mirroring of HyDraw texts.
21. Update Parts List: When quantity values change, the corresponding row gets deleted in case of grouped items.
22. Inserting custom External Port displays error.
23. Export to MDTools command fails when items have same item ID.
24. When the drawing includes a Parts List, the Convert to HyDraw command causes instability.
25. When the drawing includes a Parts List, joining a custom Connection Line (e.g. Line1) to another Custom Connection Line's tip (end) displays error and causes instability.
26. HyDraw Library Explorer: Component tab slightly overlaps.
27. When an Item ID is manually positioned, the Reassigned Item ID is not at its new location.
28. Export to MDTools: Order of CAD models linked to a model are incorrect.
29. Copied Sub-System, takes new balloon type from HyDraw option for Components.
30. In Update Parts List, the yellow Update icon does not appear for,
 - a. Components Accessories.
 - b. System Accessories.
 - c. External Port Accessories.
 - d. Item ID/Accessory ID edited by double click.
 - e. Grouped Hose ID.
 - f. Multiple Parts List.
31. In Update Parts List,
 - a. Value of design properties is not updated.
 - b. Currency data types are not updated correctly.

Date: Jan 3, 2019.

HyDraw CAD 2019 Hotfix 5.0003 - EN

Applicability: HyDraw CAD 2019 EN

Issues Resolved:

1. Updating the earlier version drawing displays error.
2. Instability when deleting/renaming the "C:\VEST" folder.

Date: Dec 07, 2018.

Release: HyDraw CAD 2019 Hotfix 5.0002 - EN

Applicability: HyDraw CAD 2019 EN

Issues:

When searching components using metric property values for flow, pressure,... from FluidPowerTools.com in the HyDraw Library Explorer, the result is incorrect.

Date: Sep 14, 2018.

Release: HyDraw CAD 2019 Hotfix 5.0001 - EN

Applicability: HyDraw CAD 2019 EN

Issues:

1. Terminator rotation incorrect in some specific cases.
2. Slip-in Valve Assembly not included in Export to MDTools.
3. HyDraw CAD Search command causing instability.
4. Schematic check changes the line weight of Connection Line.
5. Issues with part list Sorting and Group Identical Item
6. With Sub-system Child Items included the Part List is incorrect.

Date: Aug 27, 2018.