

# Configure Monochrome Plot Style in HyDraw<sup>®</sup> CAD

---

**VEST, Inc.** 3250 W, Big Beaver Road, Suite 440, Troy, MI 48084 USA

Tel: 01 248 649 9550 Fax: 01 248 649 9560


Email: [sales@VESTusa.com](mailto:sales@VESTusa.com) Visit: [www.VESTusa.com](http://www.VESTusa.com)

## Configure Monochrome plot style

1. Type CONVERTCTB command and press Enter/Spacebar in command line.

*Select File dialog appears.*

2. In the listed Plot Styles select "monochrome.ctb".
3. Click **Open**.



Select File


*The Create File dialog appears.*

4. Provide a New File name or select "monochrome.stb".

5. Click **Save**.

*The Plot Style successful creation message box appears.*

6. Click **OK**.




Create File

7. Type CONVERTPSTYLES command and press Enter/Spacebar in command line.

*The HyDraw Message box appears.*


8. Click **OK**.



HyDraw Message

*Select File dialog appears.*

9. Select "monochrome.stb".
10. Click **Open**.



Select File