

HyDraw® CAD 2020 Hotfix 09 EN

Applicability: HyDraw CAD 2020-EN with SP2 installed

Issues Resolved:

1. Hose ID numbering sequence should be Left to Right in the order of nearest to Origin.
2. In a few specific cases, Create Hose List displays error.
3. Hose List should be sorted by Hose ID.

Date: Nov 27, 2020